Audi MQB Transmission TCU Unlock Instruction

1. Enter Audi V28.67

2. Select “Health Report”.

3. We can find Fault code P170100-Transmission Control Unit Locked in TCM, Fault code 02229-Transmisson Control Module, Immobilizer Data Not Adapted.





4. Enter Special Function of Audi



5. Select Anti-theft Function.



6. Select 5th Immobilizer.



7. Connect vehicle, diagnostic tool and X-PRO G as diagram.



8. Select 5th Generation Replacement.

9. Select 5th Generation Transmission



10. Install the new vehicle ECU on target vehicle, click Ok to continue.



11. Replace succeed.



12. Exit and clear fault code of TCM, and Read DTC. P170100 Missing, Transmission is unlocked.